CERTIFIED LAND CORNER	DESTORATION

History of original corner establishment:

ESTABLISHED IN 1937 RESURVEY

Description of corner evidence found:

SCRIBED & SOUARFO CEDAR POST DOWN - Point in Ground

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2 INCH IRON PIPE WITH BRASS CAP

NEW BIT.S ASPEN 6" N12E 26.5 LINKS ASPEN 7" N84E 31. LINKS

BIN	RAM	
(2)	1)	
N 1/6		

Dated at ASTIGO Wis., this 3Rd day of	June 1978
Dated at ASTIGO, Wis., this 3Rd day of Signature ASMAN Surveyor, Registered Land Surveyor, or other duly authorized official,	Ungan Registration No. 4.85
(County Surveyor, Registered Land Surveyor, or other duly authorized official)	
Office of Register of Deeds, County of	, I hereby certify that the within
instrument was filed in this office for record on theday of	, 19
ato'clock	
(Register of Deeds)	

State of Wisconsin				
County of Langlade ss.				
I Roy mond J. Hallsy, do hereby certify that on the Jid day of June 19.78, I found evidence of the North Vi6 corner of Section 1, 2  Township 3/ North, Range 96.57, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.				
Resident witnesses:				
T31N R9E				
SOUTION!				

*again.	31N	R9E	
	1		
	1	1	!
	<u> </u>	<u> </u>	
	1	1	
	1	l	
	Sc	CTION	
		2	
	1	' !	
	!		
	}		
	<b>!</b>	<b>!</b>	

O = Corner monument restored.