CERTIFIED LAND CORNER RESTORATION

32-12Index No. E-9

History of original corner establishment:

NEVEMBER 15, 1939 RESURVEY

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP

Description of monument and accessories I established to perpetuate the original location of this corner.

RESET SAME PIPE SOURS EAST OF CORNER

,

By.....Deputy