U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(Prepared and as required by S. A-E 7.08 Wi Administrative Code)

(i repaire and as required by 6: // = /:55 //// (allimine)	
Corner was: (check all that apply)	43309102020
☐ Restored through acceptance of an obliterated evidence location	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
☐ Restored through acceptance of a found perpetuated location	
🗵 Determined to be lost and reestablished through proportionate methods.	
(Show bearings and distances to PLSS corners used for proportioning)	
☐ Restored/recovered/reestablished in a location that differs from a previously	
established position. (Show difference in plan view below.)	
\square Check here if additional information is shown on the reverse side of this form	
Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence considered in the recovery/restoration of corner.	vidence and all other

2004 - Dean A. Williams found N,S,E,W 1/4 CORNERS AND SET CORNER AT INTERSECTION OF 1/4 LINES.

Physical description of the monument set:

Signature

Date

2004 - Dean A. Williams and James Gardner set 1.3" x 30" I.P. .5' below road surface.

Describe the accessories used to perpetuate the location of the corner. Include a plan view drawing and indicate accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would aid in future recovery of the corner.

