CERTIFIED LAND CORNER RESTORATION

Index No. J-2

History of original corner establishment:

Description of corner evidence found:

4" Galvanized pipe with cap on south sade of Golf Course.

Description of monument and accessories I established to perpetuate the original location of this corner.

New PT's

 Red Pine
 1½"
 \$76E
 3! 2"

 Red Pine
 9"
 \$18W
 7! 10"

 Red Pine
 9"
 \$75W
 23!

4