SURVEY MONUMENT RECORD PUBLIC LAND U.S.


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

Identify the corner by (a) reference to the U.S. public land survey system.

O = Corner monument restored.

1/4 corner sec. 17 and 18 T33N, R11E



Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material (b) evidence you considered, and whether the monument was found or placed.

Monument was set by the C.C.C. in the 1930's. It was pulled out of the ground and buried during the construction of H'way "45" about 30 years ago. In searching I found the monument out of the ground and buried about 3" underground. I doubled the distance from the section corner to the south and the S1/16 corner and was able to locate a small possible afea for it. In futher digging I found the rock used for the tie from the 1930's survey. The rock had a cross-cut on the top and the monument was 1.4° north of the rock. When we dug in the monument we found rust from the monument when it was originally in the hole. The 4" steel pipe filled with concrete with a brass cap was set back in place.

In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a provide reference ties to at least 4 witness monuments, or, if the location is within a provide reference ties to at least 4 witness monuments, or, if the location is within a provide reference ties to at least 4 witness monuments, or, if the location is within a provide reference ties to at least 4 witness monuments, or, if the location is within a provide reference ties to at least 4 witness monuments.

(c) municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

Describe witness monuments.

Show a plan view drawing depicting (d) the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

6" maple 54'z to center H'way "45"monument reset

Orig. rock

sign with steel

post 1.5' west

Spruce

8" Maple

Red Pine

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

Same place.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?

No. 2

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

No

THOMAS R.
ARNOTT
S-887
CRANDON
WIS.

(i) I. Thomas Arnott

s-88**7**

(type or print name)
certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

2 Sept 1992

Date