
CERTIFIED LAND CORNER RESTORATION



History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found wood post down, rock mound, point intact.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set $1\frac{1}{2}$ " pipe with brass cap. New BT's

| 6" | Twin Hard | Maple | S24E | 21' | 5" |
|-----|-----------|-------|------|-----|-----|
| 411 | Hard | Maple | N79W | 71 | 711 |
| 4" | Hard | Maple | MIOE | 51 | 211 |

