			CERTIFIED	LAND	CORNER	RESTORATION
ate of	Wisconsin	1				

SS.

		E		0
Index	No	6	•	8

History of original	corner	establishment:
---------------------	--------	----------------

Corner set in the 1930 resurvey.

06/18/19 D. Tlusty found 1 ½" iron pipe with brass cap in good condition, solid in ground, top is 14" above ground. Hallisys two maple BT's overgrown. I marked new BT's described below; set an aluminum nail in low side blaze for measurement.

Maple, 13", S30E, 1.76'; Maple, 9", S88W, 9.49'; Spruce, 3", N23W, 19.41'. Set white sign post 1' north of corner monument. NAD83(2011) LCCS:

N 454303.338 E 559710.207

Description of corner evidence found:

Set 12 iron pipe with brass cap.

New BT's

Found AX squared wood post down, point intact, marks plain.

of	
OI	aymond J. Hallisy , do here at on the 2nd d
* 1	May , 19.81 , I fou of the E 1/8
evidence	of the B 1/0 Section 5 & 8
corner of.	5eculon 5 & 0
Lownship	North, Ran
	E, Fourth Principal Meridia
as describ	ed hereon; and that from this eviden
ne docoril	hed a new monument and accessor
location o	ped hereon to perpetuate the origin f this corner.
iocation o	this corner.
Resident	witnesses:
remacii	WILLIESSES.

	1 0
	1 1
l .	1
	Section 8
	Section 8
	Section 8 :
	Section 8 : 134NR9E
	Section 8 ! 134NR96
	Section 8 !
	Section 8 !
	Section 8 134NR9E

County of Langlade

0 =	Corner	monument	restored.
-----	--------	----------	-----------

81	Hard Maple	S40E	Jilin	12 -		
81	Hard Maple	s75w	91811	-3-		
7:1	Hard Maple	n45e	10'7"	E 1/8		
Signature James	md Halles	U Title	Reg. I	and Surveyor r duly authorized official)	Registra	
Office of Register o	f Deeds, County of	<u>(</u>		day of	I hereby cert	ify that the within
to'clock		3 ••••				19
	(Register of Deed	is)		*******		
2.,			D.			

Description of monument and accessories I established to perpetuate the original location of this corner.