State of Wisconsin

| \circ | = | Corner | monument | restored. |
|---------|---|---------|----------|-------------|
| () | _ | COLLICI | monument | i cotoi cu. |

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

h" iron pipe with brass can

Description of monument and accessories I established to perpetuate the original location of this corner.

Mew Pmis

| 10" | Red Maple | 548W | XXX | 81 | 3" |
|-------|------------|-------|-----|------------|-----|
|),111 | Hard Maple | M(1)M | | 71 | 611 |
| 511 | Hemlock | WisE | 1 | 5 t | 911 |

(Register of Deeds)

By.....Deputy

26th M cvember Wis., this day of Dated at..... Land Surve or 5685 Title Registration No. Signature... (County Surveyor, Registered Land Surveyor, or other duly authorized official)