State of Wisconsin

 $\bigcirc$  = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No. *U-4* 

History of original corner establishment:

Ran a random line S  $0^{\circ}$  30' W from EC 1/16 previously established, 39.737 chains to a point 1.018 chains east of E 1/16 corner between Sections 30-31. Corrected bearing of line S  $0^{\circ}$  58' E. Corrected distance 39.747 chains.

Ran a random line S 89° W from S 1/16 corner between S 29 and 30, a distance of 42.64 chains to a point 1.9 lks south of SC 1/16 corner. Corrected line and set a picket at intersection of true N-S and E-W 1/4 lines, S 88° 45' W 21.31 chains from E 1/4 line and N 0° 58' W, 19.863 chains from E 1/16 corner.

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2" iron pipe with brass cap, stamped.

Pipe projects 18" above ground.

NBTs - Red Oak 12" S 12° E 106.2 lks. scribed 1/16 BT.

3498

NBTs - Red Oak 12" S 12° E 106.2 lks, scribed 1/16 BT.
Sugar 12" N 18° E 97.5 lks, scribed 1/16 BT.
Pipe and NBTs painted blue.

T34N HILE SE 1/16 S 30 1976