10/2 0000 LANGLADE CL. ATY U.S. PUBLIC LAND Found X SURVEY MONUMENT LOCATION RECORD Section 4301012 0000 Set Township Corner Location:___ Re-set Northwest Corner Section 18 Range Re-Tied X Monument Type: SMP (Survey Marker Pin) Rolling County Coordinate: N City, Village, Town Date of Survey: 10/11/2011 Datum: Section Survey Party: C. Fieri & E. Pierce Field Book: Looseleaf Page Number: BASIS FOR MONUMENT LOCATION: (Describe method of survey and corner authentication) 3/11/1993 - M.J. Nordin searched the area for the corner and found a Railroad spike at the centerline intersection of the county roads. He accepted this position as the section corner and tied out. Location 10/11/2011 - E. Pierce and I visited this corner because we were (indicated by X) informed by the Harrison Town Chairman that a car accident had destroyed the NE tie. Intersected the three remaining ties and set an SMP at the corner location. Reset the witness monument to the NE. William SURVE Fieri, RLS - 2954 12/2/2011 Seal TIE SKETCH: Show minimum of four (4) horizontal tie distances to fixed witness monuments. Describe all monuments found or set. ● = 5/8" Iron Rod Found w/ Witness Post 5/8" Iron Rod Reset w/ Channel COUNTY ROAD SMP Note: Distances with Bearings shown were taken from tiesheet by M.J. Nordin dated 3/11/1993. M:\Tiesheets\TIES\30-10\dwg\65-13-30-10.dwg