
CERTIFIED	LAND	CORNER	RESTOR	PATION

History of original corner establishment:

Corner Established in 1937 Resurvey

Description of corner evidence found:

4 inch IRON PIPE With Brass CAP




Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T. s Red MAPLE 9" NTRE 12.8 FT, ASPEN 10" SG2E 18.6 FT Red MAPLE 6" 532W 69.7 FT

Nie die	15th day of	Donil	10 75
ignature (County Surveyor, Registered Land Surveyor, Office of Register of Deeds, County of	istered Lands	Turveyer Registr	ration No. 5-685
(County Surveyor, Registered Land Surveyor,	or other duly authorized of	fficial)	26.4.4.4
Office of Register of Deeds, County ofor nature of the strument was filed in this office for record on the	day c	ofhereby cei	rtify that the within
to'clock			
(Register of Deeds)			

State of Wisconsin County of Langlade I Raymond J. Hallisy , do hereby certify that on the 16 Th day of April , 19.28, I found evidence of the Section corner of 35, 36, 1, 2
Township 31, 32, North, Range
9,6457, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner. Desident witnesses

esident withesses:	



O = Corner monument restored.