The South Quarter corner of Section 30, T. 32 N., R. 11 E., Langlade County, WI.  Corner was: (check all that apply)  Restored through acceptance of an obliterated evidence location.  Restored through acceptance of a found perpetuated location.  Bestored through acceptance of a found perpetuated location.  Show bearings and distances to PLSS corners used for proportioning, and show original distances).  Show bearings and distances to PLSS corners used for proportioning, and show original distances).  Restored/recovered/re-established in a location that differs from a previously established position.  (Show difference in plan view below).  Check here if addition information is shown on the reverse side of this form.  Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of the corner.
---

See history on reverse side

Physical description of the monument set:

I left the existing stone monument in place.

13 S

Decrinos

ned (C)

ع Set white vinyl sign post The South Quarter corner O = corner perpetuated T. 32 N., R. 11 E., Langlade County, WI Bearings are Langlade County Coordinate System grid bearings. 2" alum. pipe with alum cap found 30 of Section 30, Top, SW corner of middle of 3 concrete steps LEGEND x 30" rebar set house utility pole Show any topographic Describe the accessories used to perpetuate the corner. Include a plan view drawing and static gps alum wm ne Lang. Co. Coordinates based on NAD83(91) published control values • 0-0 static gps rebar set 369346.88 616755.95 616764.01 616787.08 SO. LIV HOS. ES.N. GH SPK SET Bluebell Road iglade County Surveyor, as determined by me and that correct to the best of my S 1/4 corner, Sec. 30-32-11 Found 1886 Dorrs stone of record accessories found/set. Describe measuring point on bearing trees. 105 369376.74 369304.81 105 • features that would aid in future recovery of the corner.  $^{\circ}$ 4 Trediction N ~ N 21°05'11" W 42.72 Angle Road N 24° 21'59" N 55.14' S & 1609 W 35.81 I, David E. Tlusty, Recertify that the cornthis U.S. Public Landknowledge and beli THE WAS SERVED TO SERVED SERVE nail & washer found in NE face of power pole. Set MAG nail in blaze on SE face of 13" spruce West most rivet, 2' from west end, on [top of 15" CMCP Rebar set 3' south of pav't. & 5' NW of stop sign Ó ㅁ

V3 32-11

Index No.

## \_ANGLADE COUNTY

U.S. PUBLIC LAND CORNER RESTORATION

## The South Quarter corner of Section 30, T.32N., R.11 E., Langlade County, WI

Corner history:

- 1860 The original corner was established by Hiram Fellows, Deputy Surveyor. Original bearing trees marked: sugar, 8", N76°E, 14 links and a sugar, 10"
- Deleglise in FB144-21, on a road survey on the N-S ¼ line in Sec. 30 and 31 said: "Orriginal ¼ post lying down on ground. Found the point of it in the ground. Set a new post in the orriginal hole." He measured to original bearing trees: sugar, 8", N71°E, 15 links and a sugar, 12" S 1 ½°W, 6 ½ links. He marked two new bearing trees: sugar, 11", S 43 ¾°E, 23½ links and a pine, 20", N69°W, 57¾ links.
- 1882 (5208.72') but he did not describe this corner or the other one he went to B.F. Dorr, in FB140-110, measured from this corner north 78.92 chains
- 1883 He did not describe this corner. B.F. Dorr, in FB144-7, measured from this corner south, 81.72 ch (5393.52').
- 1885 B.F. Dorr, in FB140-26, measured the N-S  $\frac{1}{1}$  line in Section 30 as 78.88 chains (5206.08').
- tapering pine post four feet long, and five to five and half inches square at the top, with a nail head in the top, directly over the hole in the stone. The top of said stones is four feet below the surface of the ground..." under said hole, and under the stone, is a one and quarter inch hole in the ground six inches deep filled with stone coal. Over the hole in each stone filled with stone coal. Said hole is the point from which to measure. thick. In the top of each of the above stones is a half inch hole, 2 inches deep quarter post of said section 30, a bluish boulder, 9 x 18 inches and 12 inches line of First Avenue on the straight section line, I have set.....at the southevidence he set for this corner: Dorr, on the recorded Plat of Reeve, gives a detailed description of the "That to permanently establish the center Over the hole in each stone is a Directly
- in road." Former surveyor Kelly, on tie sheet, said: "Located evidence of Hutchinson corner. Set new wit. Monument 11-17-86. Set R.R. spike over existing iron Set new wit. Monument 11-17-86.
- 2009 corner as Kelly stated. In the available records, there is no mention of any monument set other that Dorr's stone in 1885. On Aug 29, 2009, using a exposed top surface as 18" x 10". Also found hole in the stone, filled with coal, as mentioned by Dorr. I accept this stone as the best evidence of the nothing below the existing railroad spike. County backhoe, we dug for the corner evidence mentioned above. For nothing below the existing railroad spike. At 2.5' deep, found a  $1" \times 24"$ Dave Tlusty, I can find to record that indicates that Hutchinson was at this original corner location. I set a plastic encased magnet on the SE edge of this stone and reset the 1" iron rod found, on the NW edge of the stone. The railroad spike (Kelly's) found was N 21°28' E, 2.30 feet from the stone found. The 1" iron rod found was S 3°21' W, 1.15 feet from the stone found. I set and measured the ties shown on Page 1. At 6.0' deep, found the stone mentioned by Dorr, which I measured the I accept this stone as the best evidence of the oundron

Page 2 of 2