CERTIFIED	LAND	CORNER	RESTORATION

History of original corner establishment:


Index No. AZ - 3Z-11 ZZ - 33-11

No evidence of a corner was found.

Only measurements found were made by the C.C.C. in the '30's.

Description of corner evidence found:

None



Description of monument and accessories I established to perpetuate the original location of this corner.

Set railroad spike in road for 1/16 corner.

1699.70' (1700.82' C.C.C.)

1377.84' (1378.74' C.C.C.)

Following accessories were made to the corner set:

- 1. iron pipe set North 33.00 feet
 2. 16" cedar S34E 29.63 feet no blaze, east end of row of cedar
 3. 14" cedar S28W 27.12 feet no blaze, west end of row of cedar
 4. Power Pole N55W 52.35 feet

Dated at	, 19_92_
Signature V Registration Registration	
(County Surveyor, Registered Land Surveyor, or other duly authorized official) County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of しているとみります。 I hereby certify	
instrument was filed in this office for record on the day of June	that the within 1992
at 3:10 o'clock P. M.	
Tack Musty	•

COUNTY SURJEMOR (Register of Deeds)