T33N R9E	State County of I	el K. Pl on the anuary he Qu Sec 33 st Fo nereon; and a new m hereon to nis corner. nesses:	ecger 12th 12th 12th 12th 12th 12th 12th 12th	34 &, Nor incipal om this t and a late the special of the spec	day, I found 35 th, Range Meridian, s evidence
	T3		1		

T33N		R9E		
1 1 1		 		
) 1/4 	_ S	35	 	
<u>!</u>	 	 		

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. X-17

History of original corner establishment:

Original corner established by H.C. Fellows, Gov. deputy surveyor in 1860 from which birch 14" bears N75E 13 links and sugar 12" bears N73W 33 links.

Description of corner evidence found:

Recovered an old 1" iron pipe with iron cap stamped: Monument projects 24" above ground.

OBT unknown origin

Maple 6"

Maple 5"

Black spruce 14" S16W 31.0 ft.

1/4 34|35

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced old monument with a $2\frac{1}{2}$ " iron pipe with brass cap stamped: Monument projects 12" above ground Marked NBTs:

S20E 19.46 ft. \$56W 19.16 ft. 1/4 34 35

S1537 - 1982

T33N R9E

Maple 6" N36E 34.60 ft. Scribed 1/4 - B.T.

Dated at Rhinelander , Wis., this 22 day of April , 1982

Signature Occupic Title Registered Land Surveyor Registration No. 1537

(County Surveyor Registered Land Surveyor, or other duly authorized official)

(Register of Deeds)

y......Deputy