
## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

HISTORY OF ORIGINAL CORNER ESTABLISHMENT AND SUBSEQUENT RESTORATION AND DESCRIPTION OF ANY RECORD, MONUMENT OCCUPATIONAL, TESTIMONIAL OR OTHER EVIDENCE CONSIDERED:


The original corner was established in 1860 by Hiram C. Fellows. Original Bearing Trees: Hemlock 8" N13W 8lks., Hemlock 10" N15E 10lks. Webley found this corner in 1917 but did not describe it. Kowalke and Borth, in 1936, "Found 3" galvanized iron pipe with stamped cap set by County Surveyor". On 8/31/98, Don Buza and Gerry Bahar found the 3" galv. pipe in a fence intersection, accepted as corner location, and tied it



CORNER WAS: (CHECK ALL THAT APPLY)

- □ RESTORED THROUGH ACCEPTANCE OF AN OBLITERATED EVIDENCE LOCATION
- RESTORED THROUGH ACCEPTANCE OF A FOUND PERPETUATED LOCATION
- CONSIDERED A LOST CORNER AND REESTABLISHED THROUGH LOST CORNER PROPORTIONATE METHODS (INCLUDE A PLAN VIEW DRAWING SHOWING DISTANCES AND DIRECTIONS TO OTHER PUBLIC LAND SURVEY CORNERS USED FOR PROPORTIONING AND DETERMINING THE CORNER LOCATION)
  RESTORED OR REESTABLISHED IN A LOCATION THAT DIFFERS FROM A PREVIOUS RESTORATION OR REESTABLISHMENT (INCLUDE A PLAN VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND)
- CHECK IF THERE IS ADDITIONAL INFORMATION ON BACK

DESCRIBE THE MONUMENT AND ACCESSORIES USED TO PERPETUATE THE LOCATION OF THE CORNER, (INCLUDE A PLAN VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND) ALSO INCLUDE FOUR TIES TO THE SECTION CORNER AND DESCRIPTION OF THE TIES.



DANIEL E. HIGGINBOTHAM

IO) CERTIFY THAT THE CORNER LOCATION SHOWN ON THIS RAUNDED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS U.S. JEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST

