= Corner monument restored.

State of Wisconsin

I Raymond J. Hallisy , do hereby

County of .. Langlade -- ~

SS.

VEDTICIED.	1 ARID		RESTORATION	
.PRIIPEPII	IANI	LURINER	RESTURATION	

Index No. 7-25

History of original corner establishment:

Corner set in the 1930 resurvey

Description of corner evidence found:

4" pipe with brass cap, rock mound.

RIIE 25 30 AZE

Y4

Sept 5, 1934

Description of monument and accessories I established to perpetuate the original location of this corner.

## New BT's

5"	Ironwood	Sloe	14.91
611	Hard Maple	S58W	9.8!
5"	Hard Maple	NSOM	7.4!
511	Basswood	S67E	3.71