

LANGLADE COUNTY U.S. PUBLIC LAND CORNER RESTORATION

The Southeast corner of Section 7, T. 34 N., R. 9 E., Langlade County, WI.

Corner was: (check all that apply)

4340907 0000

- Restored through acceptance of an obliterated evidence location.
- Restored through acceptance of a found perpetuated location.
- Determined to be lost and re-established through proportionate methods.
- Show bearings and distances to PLSS corners used for proportioning, and show original distances).
- Restored/recovered/re-established in a location that differs from a previously established position.
- (Show difference in plan view below).
- Check here if additional information is shown on the reverse side of this form.

Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of the corner.


The original corner was established by James L. Nowlin in 1864. Original bearing trees: brich, 22, S76E, 12 links, sugar, 12", N60W, 7 links, birch, 6" and sugar, 4" (no meas. data in notes for last two trees). In the 1930's resurvey, Darwin Hintz said: to orig. sec cor. Rest. pine stp. 20, N50W, 92.4; birch stub, 10, N30E, 130.6. A 1964 corner record by the State Highway commission said: "sec. cor set by previous survey. Reset after construction with concrete post with brass cap marked."

April 30, 2018, D, Tlusty found 5" square concrete marker with brass cap in top. Top portion of marker is broken off, base is still in ground. Accepted concrete marker as a perpetuation of the original corner location and replaced it with a 1" (OD) aluminum rod monument with 3 1/4" dia. aluminum cap flush with ground. I buried the two concrete pieces horizontal in the ground below the top of the monument set. Perpetuated the location as shown below.

Physical description of the monument set:

Set a 1" (OD) x 42" barbed bottom aluminum monument with magnet and 3-1/4" stamped aluminum cap, flush with ground. Set a 6' green steel channel post with "Forest Boundary" sign, 0.85' east of corner monument.

Describe the accessories used to perpetuate the corner. Include a plan view drawing and accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would aid in future recovery of the corner.



Langlade County Coordinate system values
 Datum: NAD83(2011)
 N 448997.35
 E 556002.69

Index No. J 5 34-09

O = corner perpetuated
 The Southeast corner of Section 7,
 T. 34 N., R. 9 E.,
 Langlade County, WI

I, David E. Tlusty, Registered Land Surveyor, as Langlade County Surveyor, certify that the corner location on this record was determined by me and that this U.S. Public Land Survey Monument Record is correct to the best of my knowledge and belief.

Field book 26-28