O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. 25 - 7

History of original corner establishment:

349

Original corner established by H.C. Fellows, deputy surveyor, in 1859 from which Cedar 8" bears S60°E 8 links and Tamarack 10" bears N35°W 9 links. In 1938 Langlade County surveyors found evidence of original corner. Evidence of original Tamarack N35°W 9 links.

Marked NBT - Birch 6" S60°E 25.15 links

Description of corner evidence found:

Recovered a 4" iron pipe with a 4" diameter brass cap - stamped: Monument projects 4" above ice of beaver flowage.

T34N R9E S32 1 4 S5 T.K. D.H.

Description of monument and accessories I established to perpetuate the original location of this corner.

Monument left as recovered.

Marked NBT's:

Black Ash 6" N4°E 42.0 links

Black Ash 5" N67°E 30.4 links

Maple 7" S63°E 27.0 links

scribed 1/4 B.T.

Dated at	Rhinelander	٠, ١	Nis., this	12th	day of	March	, 19.81
Signature	Dave K. (County Surv	Pleagen eyor, Registered I	Title R	egistered	Land Sur	veyor R	egistration No. 1537
Office of Renstrument	egister of Deeds, (County of Thice for record	· • • • • • • • • • • • • • • • • • • •			I herel	oy certify that the within
••••••	(Reg	ister of Deeds)	······································	•••••••••••••••••••••••••••••••••••••••	·		