O = Corner monument restored.

S.C.

## CERTIFIED LAND CORNER RESTORATION

Index No. V-13

History of original corner establishment:

Original corner established by J.L. Nowlin, deputy surveyor, in 1865 from which Tamarack 5" bears N83°E 15 links and Tamarack 5" bears S44°W 30 links.

Corner recovered in 1937 by Langlade County surveyors.

Set a 4" iron pipe filled with concrete and brass cap.

Marked NBT's -

Tamarack 5" N72°W 64-1/2 links

Tamarack 5" N8°E 72-1/2 links

Tamarack 5" N80°E 78 links

Description of corner evidence found:

Recovered old monument laying on ground covered by moss, also recovered two old cedar stakes in hole of corner position. Brass cap of old monument stamped:

Recovered OBT's Tamarack 5" N8°E 72.5 links - now a rotted stump, scribed S28-BT.

Tamarack 5" N72°W 64.5 links, scribed S28 BT.

Tamarack 5" N80°E 78.00 links - now dead - scribed S27 BT.

Tamarack 5" N80°E 78.00 links - now dead - scribed S27 BT.

Langlade County

T34N R10E

28\_27

33 34

11-9-37

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2-1/2" iron pipe with screw-on brass cap stamped:

Monument projects 12" above ground.

Marked NBT's -

Tamarack 5" S31°E 14.35 feet

Spruce 6" S68°W 40.95 feet both scribed S.C. BT.

s.c.  $\frac{28}{33} + \frac{27}{34}$ 

\$1537-1980

T34N R10E

Dated at	Rhinelander	. Wis., this	26th	day of	November	19.80
Dated at		, ** ***, *****				

Signature Daniel K. Pleogram Title Registered Land Surveyor Registration No. S-1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of......, I hereby certify that the within

at.....o'clock...... M.

(Register of Deeds)

Sy......Deputy