O = Corner monument restored.

	LAND	CODMED	DECTORATION	
EKIIFIED	LAND	CORNER	RESTORATION	

History of original corner establishment:

C

No evidence of any previous corner.



Index No. 4-16

Description of corner evidence found:

Corner established by subdividing the SE 1/4 section 34 T34N R10E. Location of SE 1/16 is N2-21-12W, 1605.847 feet of E 1/16 between sections 34-34-10 and 3-33-10 and S-2-21-12E 1605.862 feet of EC 1/16 section 34.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped:

Monument projects 12" above ground.

Marked NBT's -

Tamarack 6" East 12.90 feet Tamarack 7" N17W 12.85 feet

Tamarack 6" S39W 3.10 feet

T34N R10E
SE $1/16 \stackrel{S}{+} ^{34}$ S1537-1980

Dated at Rhinelander , Wis., this 26th day of November , 19 80

Signature Janual K. Pleague Title Registered Land Surveyor Registration No. S-1537

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

(Register of Deeds)

By......Deputy