

CERTIFIED LAND CORNER RESTORATION

34-12

Index No. Z-9

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:

Resurvey in 1935-36 by Charles W. Berth: Set and scribed new cedar stake.  
New BT cedar 7 S 46 $\frac{1}{8}$ °E 16.6';  
6 S 89°W 29.5'

I Christy T. Hauge, do hereby certify that on the ninth (9th) day of July, 1962, I found evidence of the southwest corner of Section 33 Township 34, North, Range 12 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Cedar stake cut off but still in same location as set by Berth. B.T.'s cut off in timber trespass case. Stumps located.

Resident witnesses:



.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set brass cap welded into a 4 foot section of 1 $\frac{1}{4}$ " pipe. Pipe extending 2 $\frac{1}{2}$  feet above ground.

New BT cedar 5.6" N 38°E 9.5' (compass set at 0°) Markings S' 33 BT

New BT cedar stump 16" S 44° E 34' (compass set at 0°) Markings S 4 B.T.



Dated at Antigo, Wis., this 9th day of July, 1962.

Signature Christy T. Hauge Title Forester, W. C. D. Registration No. ....  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of ....., I hereby certify that the within instrument was filed in this office for record on the ..... day of ....., 19..... at ..... o'clock ..... M.

.....  
(Register of Deeds)

By ..... Deputy

○ = Corner monument restored.

PLSS field condition report

Date: 4/21/2020 Time of day: 8:00 AM

By: Cody Brauns

Section 33 Town 34 Range 12E  
(circle corner location on diagram)



4341232.0000

Does the monument appear to be tilted, smashed, uprooted, covered or otherwise damaged by the windstorm?

YES  NO

*Down tree on monument*

Are any bearing trees broken, uprooted, missing or otherwise damaged by the windstorm? YES  NO

*Monument leaning ~ 30-40°*

*Cedar stump gone*

*Cedar BT intact*

TAKE PICTURES

For the first four pictures, do them in this order:

Looking north, looking east, looking south, looking west and, by standing about 6 feet behind the monument, include the monument in each picture.

Then take a picture of the top of the monument, close enough to be able to read what is stamped on the cap. Make sure all pictures are in focus.