CERTIFIED	LAND	CORNER	RESTORATION

History of original corner establishment:



Description of corner evidence found:

R.R. SPIKE IN ROAD PAVEMENT ON LINE BETWEEN SECTION CORNER AND 1/4 SECTION CORNER IDENTIFIED BY RESIDENT WITNESS AS W/8 CORNER.

> I SET 1½" I.P. WITH BRASS CAP
> AS REFERENCE CORNERS TO THE
> WY8 CORNER SECTION 32 T34N-RISE
> 5 T33N-RISE COR. 50'N

BRASS CAPS MARKED;

Description of monument and accessories I established to perpetuate the original location of this corner.

NBT 12" YELLOW NBT 8"OAK-542°E-31.82" 526°W 31 68' 20 TRUNK DD. TRUNK DD.	
NEW DEARING TREES BLAZED NOT CHEST	

HIGH AND MARKED WITH A + AT BASE.

Dated at EICHO , Wis., this 13th day of OCTOBER , 1974

Title REGISTERED LAND SURVEYOR Registration No. S. 1098 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

instrument was filed in this office for record on the ______day of _______, 19...... at.....o'clock...... M.

(Register of Deeds)

.Deputy