N 88°38'07" E 2491.40' (1939 resurvey - \$ 88°41' W, 2500.08') 1247.70 1247.70' 1211.47' 120,61 1125.09' SE corner, Sec. 13 FOUND 1" IRON PIPE IN ROAD 1/16th corner, Sec 13 & Sec 24 Quarter corner, Sec 13 & Sec 24 FOUND 4" IRON PIPE WITH BRASS CAP Set a 1" x 30" iron pipe at mid-point between the the quarter corner and section corner shown. The corner falls 1' off gravel shoulder and approx. 16 feet from the center of pavement of STH "52". Langlade County coordinates obtained by direct O 1" x 30" iron pipe set static GPS sessions on the corners shown The pipes set each way from the SCALE: 1/16th corner are marked with 6' green 4 379517.256 678454.893 SE corner 13-32-12 1" = 200' steel channel posts with "Langlade 5 379457.914 675964.204 S1/4 x 13-34-12 County Forest Boundary" signs. I, David E. Tlusty, Langlade County Surveyor, do hereby certify that I have made a survey FB3 to set the East 1/16th corner on the South line of Section 13, T32N, R12E, as shown hereon. I further certify that this map is a true and correct representation of said survey and DATE: that this survey is correct to the best of my knowledge and belief. Corner restoration forms are on file for all monumented corners shown. 6/10/2005 TOWN OF: Price Nov. 16, 2007 David E. Tlusty, S-1390 **Langlade County Surveyor TOWN CODE:** LOCATION: SECTION: RANGE: DWG. #:

DRAWN BY: D. TLUSTY

REF. FILE:

13 TOWNSHIP: 32 12

..SURVEYS/T32N/133212