



Langlade County Coordinates  
NAD83(2011) datum

	N	E
NW cor Sec 6	428056.53	550525.12
W 1/4 corner	425409.80	550509.50
E 1/4 corner	425680.25	556169.26
NE cor Sec 6	428317.07	556208.75
N 1/4 corner	428298.60	553566.60
CN 16th cor	426920.70	553512.08
NE 1/16th	426955.91	554850.46
S 1/4 corner	422873.76	553351.96
SE cor Sec 6	422979.53	555998.80

Center North (CN) 1/16th corner  
I set a 1" (ID) x 36" iron pipe with 2" aluminum cap, up 0.6'. Set a 6.5' steel channel post with County Forest Boundary sign, 1' east of corner  
Found CPI iron pipe, S73E, 2.4'  
BT: 7" Black ash, N63W, 7.95'  
BT: 9" spruce, N35E, 9.2'

Northeast (NE) 1/16th corner  
I set a 1" (ID) x 36" iron pipe with 2" aluminum cap, up 0.5'. Set a 6.5' steel channel post, N78W, 2.0'  
Corner falls 0.5' east of the CPI monument, bent and leaning.  
BT: 6" tamarac, N68W, 19.45'  
BT: 11" tamarac, N58E, 35.2'

Section 6 was surveyed and divided in 1982, with interior property corners set, as shown on a Consolidated Papers Inc. survey map filed in Langlade County Surveyor records as map #30266. An examination of that map indicates that the Center North (CN) sixteenth corner and the Northeast (NE) sixteenth corner were not set correctly.

This survey was ordered by the Langlade County Forestry Department to correct the above two mentioned corners. The survey work was completed in May, 2024 and upon attempting to set monuments in the correct location for the above two mentioned corners, it was found that Consolidated had set those two corner monuments in the correct location, but there mapping of the survey work was wrong.

In completing this survey, I replaced the two Consolidated monuments with the monuments described hereon. The corrected CN corner fell within 2.4 feet of the Consolidated monument and the corrected NE corner fell within 0.5' feet of the Consolidated monument, found bent and leaning. See corner descriptions above.

LEGEND  
○ 1" (ID) x 36" iron pipe set as noted  
— Langlade County Forest boundary  
Bearings are Langlade County Coordinate system grid bearings and are referenced to section lines shown.  
CPI angles are shown for comparison to measured (M) angles  
CPI distances shown as (0.00')

I, David E. Tlusty, Professional Land Surveyor, do hereby certify that by the direction of the Langlade County Forestry Department, Al Murray, Administrator, I have made a survey of part of Section 6, Township 33 North, Range 9 East, Langlade County, Wisconsin, as shown and described hereon. I further certify that this survey has been completed in compliance with A-E 7 of the Wisconsin Administrative Code; that this map is a true and correct representation of said survey and that this survey is correct to the best of my knowledge and belief.

David E. Tlusty  
Wisconsin Professional Land Surveyor S-1390  
Deerbrook WI  
LAND SURVEYOR

Surveyed April-May, 2024

David E. Tlusty, PLS  
Deerbrook, Wisconsin 54424

Survey for  
Langlade County  
Forestry Department  
Section 6, T. 33 N., R. 9 E.,  
Langlade County, WI.

RECORD # 30043  
LANGLADE COUNTY SURVEYORS OFFICE  
DATE FILED: 6/12/24 BY: D.T.

SCALE: 1" = 150'	DATE: April - May, 2024	DRAWN BY: dt	MAP #:
---------------------	----------------------------	-----------------	--------