٠.	150	. 1 1	íy,	1.	٠)

	CERTIFIED LAND CORNER RESTORATION
State of Wisconsin County of Langlade	SS.
I found evidence of the North Township 33 North	, do hereby certify that on the 15th day of June 19 78 west Section corner of Section 9 Range 14 East Fourth Principal Meridian, as described lence I established a new monument and accessories as described hereon to perthis corner:
Description of original monume	nt and accessories and subsequent restorations:
Hemlock, 10", N29°E, 50 I distance given); Spruce,	Nowlin and 9. 80.00 chains set post corner to sections 4,5,8 and 9. ks.; Spruce, 8", N15°W, 15 1ks.; Spruce, 10" (No bearing or 7", (No bearing or distance given) West, 2 chains, Cedar ns, stream, 10 1ks. wide, runs SW.
Description of corner evidence	found:
of the Hemlock stump. Po	cop rotted off. Point of post in the swamp. No evidence ossible spruce stump mound, N15°W, 15 lks. o and 7.0 chains west stream runs SW. dence that was reported found in 1936 by C.J. Priegel.
I replaced the post point monument 5 feet long, will 1978, S-1107. From with Spruce 5", S33°E, 8.26 fe	found with a 2 inch inside diameter Berntsen aluminum th an aluminum cap stamped: T33N R15E, S4, S5, S8 and S9, the following bear: Spruce 7", N54°E, 20.21 feet, eet, Tamarack, 8", S6°W, 17.10 feet, Tamarack, 11", sign post, NE, 0.50 feet.
	Resident witnesses.
Sec. 9	Dated at Laona Wisconsin, this 25 day of July 19.78 William B. Cochrane Title Survey Technician (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. S-1107 Office of County of I hereby certify that the within instrument was filed in this office for record
Corner monument restores	on the day of 19 and was filed in Book No. Page No. of County Records.
	SignatureTitleTitle

Township 33 North Range 14 East Section 9 Index No. E-9 Page No.