••••			
	T33	NIR9	5
	T33	NIR9	=
		N, R90	5
		N, R90	=
		N, R9	<u>=</u>

State of Wisconsin

I WILLIAM F. KELLY , do hereby certify that on the 9th day

of Dec. , 19.81..., I found

evidence of the SE corner of SEC. 32

9 EAST....., Fourth Principal Meridian,

as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

County of LANGLADE

location of this corner.

Resident witnesses:

SS.

O = Co	rner monu	ment i	restored.
--------	-----------	--------	-----------

CERTIFIED LAND CORNER RESTORATION

Index No. A-9

T32N-R9E

IN ROS

History of original corner establishment:


ORIGINAL CORNER ESTABLISHED BY HIRAM C. FELLOWS IN SEAT., 1860.

IRON BAR SET BY D. HINTZ ABOUT 1936

RHINELANDER PAPER SET WIT MON.

Description of corner evidence found:

KON BAR AND 4" ALUMINUM CAP WITNESS MONUMENT, FOUND IN PLACE. SET PK NAIL OVER KON BAR. MARKED ONE NEW WIT.



Description of monument and accessories I established to perpetuate the original location of this corner.

BT BT PK NAIL SET IN CROSS	HWY. "J" POWER POLE \$109-561	532 533 55 54 COR CH So.
Dated at ELCHO	, Wis., this9世 day of	DEC. , 19.81
Signature Mlleam S. Ro (County Surveyor, Re	Title COUNTY SURVEYOR gistered Land Surveyor, or other duly authorized offici	Registration No. 1098
Office of Register of Deeds, County nstrument was filed in this office fo	of	, I hereby certify that the within
(Register of	Deeds)	