## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(Prepared and as required by S. A-E 7.08 Wi Admi	nistrative Code)
Corner was: (check all that apply)	
Restored through acceptance of an obliterated evidence location	4331002 3500
Restored through acceptance of a found perpetuated location	
☐ Determined to be lost and reestablished through proportionate methods.	
(Show bearings and distances to PLSS corners used for proportioning)	
☐ Restored/recovered/reestablished in a location that differs from a previously	
established position. (Show difference in plan view below.)	
$\square$ Check here if additional information is shown on the reverse side of this form	
Describe record evidence, recovered physical evidence, occupational evidence, testimo	onial evidence and all other
evidence considered in the recovery/restoration of corner.	

1865 - Original Corner was never established by James McBride Original notes had no mention of a meander corner on this line.

2006 - Dean A. Williams found during a Rasmussen suvey that the section line as it lies today leaves the the land and travels across Summit Lake even from the original Summit Lake Plat of 1888

Physical description of the monument set:

2006 - Dean A. Williams set 1.9" I.P.

Tied with set .75" x 30" I.R.'s for witness monuments.

Describe the accessories used to perpetuate the location of the corner. Include a plan view drawing and indicate accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would aid in

