SECTION\_\_\_3

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

NOTE THIS FORM IS INTENDED AND DESIGNED TO FULFILL ALL REQUIREMENTS OF WISCONSIN ADMINISTRATIVE CODE, CHAPTER A-E 7.08 U.S. PUBLIC LAND SURVEY MONUMENT RECORD (3) ( $\alpha$ ) ( $\alpha$ 


| WITH SAID REQUIREMENTS.       |                  |          |   | ٦ , |
|-------------------------------|------------------|----------|---|-----|
| (a) CORNER LOCATION:          | TOWNSHIP33 NORTH |          |   | 4 1 |
|                               | RANGE10EAST/#EST | <b>X</b> | 2 | _   |
| TOWN/ <del>CITY/VILLAGE</del> | <u>UPHAM</u>     |          | Ψ |     |
| COUNTY                        | LANGLADE         |          |   |     |

(b) (f) (g) (h) DESCRIPTION OF MONUMENT FOUND AT THIS CORNER AND IF IT WAS ACCEPTED, STATE ALL EVIDENCE (MATERIAL, TESTIMONIAL, OCCUPATIONAL, PLATS, RECORDS, OTHER MONUMENTS) USED AS BASIS FOR ACCEPTING. IF NOT ACCEPTED OR IF NOTHING WAS FOUND, STATE EVIDENCE USED AS BASIS FOR ESTABLISHING LOCATION. IF REESTABLISHED THROUGH LOST CORNER PROPORTIONATE METHODS, INDICATE ALL MONUMENTS, DISTANCES AND DIRECTIONS USED TO ESTABLISH. INDICATE TYPE OF MONUMENT FOUND OR SET AND SIGN POST.

HAD TIE SHEET BY KELLY FROM 1981. FOLLOWING LINE OF NO TRESSPASSING SIGNS AND PINK / ORANGE RIBBON, COULD NOT FIND CORNER. SET GPS POINT OUT IN SWAMP, WENT ON COMPASS BEARING / DISTANCE, FOUND CORNER. TIES ARE ALL GONE. CORNER IS NOT ON LINE WITH NO TRESSPASSING SIGNS / RIBBON. CORNER IS ABOUT 1300 FEET EAST OF OLD RAIL ROAD

GRADE AND 100 FEET SOUTH OF NO TRESSPASSING SIGNS.
FOUND 4" STEEL PIPE WITH BRASS CAP STICKING 20" ABOVE SURFACE. PAINTED PIPE ORANGE. PUT FIBERGLASS POST NORTH & SOUTH OF PIPE, PAINTED ORANGE. BLAZED 4 TREES AND PUT NAI IN BLAZE. DISTANCE IS TO CENTER OF NAIL HEAD. PUT BEARING TREE SIGN CHEST HIGH ON TREES. HELD PIPE AS CORNER.

(c) (d) (e) PLAN VIEW OF CORNER WITH TIES TO AT LEAST 4 WITNESS MONUMENTS. IF IN DISAGREEMENT WITH PREVIOUSLY ESTABLISHED CORNER, SHOW THE DISTANCES BETWEEN THE TWO CORNERS AND ALSO INDICATE THE TIES TO THE DISPUTED CORNER.



1-17-03

DATE

≺IGNATURE

State of Wisconsin

I WILLIAM F. KELLY , do hereby certify that on the 13th day of FεB , 19 81 , I found evidence of the EAST 1/1 corner of Sec. 4

Township 33 , North, Range

10 EAST Fourth Principal Meridian,

as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

KNIGHTS TEMPLAR CLUB

County of LANGLADE

location of this corner.

Resident witnesses:

SS.

## CERTIFIED LAND CORNER RESTORATION


Index No. C - 13

History of original corner establishment:

DRIGINAL CORNER ESTABLISHED By HIRAM C. FELLOWS IN 1860.

Description of corner evidence found:

FOUND IN PLACE, 4" BRASS
CAP MONUMENT, SET DURING
RESURVEY OF TOWNSHIP IN 1938.
MARKED NEW WITNESS TREES.



Description of monument and accessories I established to perpetuate the original location of this corner.

| •            | HADE COUNTY                    |   |
|--------------|--------------------------------|---|
| ALL NEW BT'S | T33N, RIDE                     | \ |
|              | 4" BRASS CAP MONUMENT - 45 4 3 |   |
| PK NAIL      | B-15-38                        | / |
| (            |                                |   |

| Dated at ELCHO  | , Wis., this | 13#                       | day of | F€B        | , 19 <u>8</u> l         |
|---|--------------|---------------------------|--------|------------|-------------------------|
| Signature Mellan S. Kel<br>(County Surveyor, Registe                                | Title        | COUNTY<br>or, or other du | SURVEY | OR Regi    | stration No. 1098       |
| Office of Register of Deeds, County of instrument was filed in this office for reat | cord on the  |                           | day of | , I hereby | certify that the within |
| (Register of Deed   | ds)          |                           |        |            |                         |