State of Wisconsin

VEDTICIED.	IVND	CODNED	RESTORAT	
CERTIFIED	LAND	CURNER	RESIDENT	IUI

Index No. V-W- 21-22

History of original corner establishment:

Established in the Dependent Resurvey and Extension Survey in 1931, of Sections 26, 35, & 36.

Description of corner evidence found:

2" iron pipe with brass cap.

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

Hard Maple 10" \$76E 12' 3" Hard Maple 7" \$32E 17' 9" Basswood 10" N34W 2' 5"

O = Corner monument restored.