1	1 1
seletion	Section -
22	23
	M.C. SGAME
	Section .
5eafiu~ 21	} 26
1	
1	

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION



History of original corner establishment:

1930 resurvey.

Description of corner evidence found:

4" iron pipe with brass cap on the west side of Game lake.

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

12" Oak N68W 4.3 Ft.

10" Red Maple S86W 10.3 "

20" Oak S15W 26.6 "

5" Red Maple S55E 12.6 "

