CERTIFIED	LAND	CORNER	RESTORATION
-----------	------	--------	-------------

	-11=	>
Index	No.	5

History of original corner establishment:

SS.

ORIGINAL CORNER ESTABLISHED By HIRAM C. FELLOWS IN 1860.

	22	_ #	

	Kelly do hereby
of Feb.	, 19.81, I found
	SE
corner of 555	. 33
Township34.	, North, Range
10 EAST	Fourth Principal Meridian,
as described hereon;	and that from this evidence
I established a new	monument and accessories
	to perpetuate the original
location of this corne	er.

iocation c	n this corner.	
Resident	witnesses:	

State of Wisconsin

County of LANGLADE

•	 	 	 	 	•••••	•••••	 
	 	 	 	 <b></b>			 

T34 N, RIOE
1 1 1
1 1 1
<del>-</del>
i i i
1 1 1

O = Corner monument restored.

Description of corner evidence found:

FOUND 4" GALVANIZED CAP IN PLACE.
HONUMENT WAS SET DURING RESURVEY
OF TOWN SHIP IN 1938.

LOCATED WITNESS TREES.



William & Felly

Description of monument and accessories I established to perpetuate the original location of this corner.

	5" MAPLE &	ALL BT'S EXISTING	
X.	LINES 7	<b>1 1 1 1 1 1 1 1 1 1</b>	33 34 4 3
Non	6" SPRUCE	4" GALV. CAP -	

1					
Dated at ELCHO	., Wis., this	5 th	day of	FEB.	, 19.81
Signature William J. Pill (County Surveyor, Registere	Title	OUNTY or, or other d	SURUEYOF	Regi	stration No.1098
Office of Register of Deeds, County of instrument was filed in this office for reco	·			, I hereby	certify that the within
ato'clock				SE	E
(Register of Deeds	)			OVE	R

EMERSURED KERLY BS:
7' DOUBLE MARLE, NISW, 28.61 FF. TO NAIC IN EAS. 1008 D.Tusty LB 22-32

FDDED BT SILVS TO BOTH. SPRUCE, 7" G. TO NAIC