State of Wisconsin

County of Langlade

SS.

Index No. X-15

History of original corner establishment:

No evidence of any previous corner



Description of corner evidence found:

Corner established by subdivision section 34, T34N-R10E. C 1/4 corner sets S3-24-50E 2859.648 feet of N 1/4 corner, S83-10-44W 2325.959 feet of E 1/4 corner, N3-24-50W 3224.438 feet of S 1/4 corner, N83-10-44E 2588.941 feet of W 1/4 corner.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a railroad spike 4 feet south of centerline of C.T.H. "T".

Set two 1-1/2" I.D. iron pipes with brass caps for witness corners, stamped:

Monuments projecting 24" above ground.

B.O.'s to true corner Power Pole #3410-34L6-S63W 86.00 feet.
sign post Brady Lane - N52W 39.95 feet.

#1	#2 T34N R10E			
T34N R10E				
$c_{1/4} + \frac{s_{+}^{34}}{4}$ w.c.	$c_{1/4} = \frac{s_{+34}}{4}$ W.C.			
N40E - 40 ft.	S56W-100 ft.			
S1537-1980	S1537-1980			

Dated at Rhinelander	, Wis., this.	26 t h	day of	November	, 19.80
Signature Daniel K. Pleage (County Surveyor, Register	Title	Registered	Land Surv	eyor Ro	gistration No. S-1537
Office of Register of Deeds, County of instrument was filed in this office for recat				, I hereb	y certify that the within

O = Corner monument restored.

v......Deputy

(Register of Deeds)