State of Wisconsin									
County of <u>LANGLADE</u> ss.									
I. WILLIAM F. KELLY., do hereby certify that on the									
Resident witnesses:									
T3ON RIIE									
1 1 1									
i i i									

O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No. J-5

History of original corner establishment:


ORIGINAL CORNER ESTABLISHED BY WILLIAM T. BRADLEY IN OCT., 1853.

Description of corner evidence found:

ORIGINAL CORNER REMONUMENTED By M. HUTCHISON APPROX. 1911.

HUTCHISON CORNER IDENTIFIED WITH REBAR IN 1930'S.

SET NEW RR SPIKE OVER REBAR AND SET A 3"x 42" ALUMINUM CAP WITNESS MONUMENT.



Description of monument and accessories I established to perpetuate the original location of this corner.

THE COUNTY OF SOLE SOLE SOLE SOLE SOLE SOLE SOLE SOLE
Dated at ELCHO, Wis., this 17th day of November, 1982
Signature William & Kelly Title COUNTY SURVEYOR Registration No. 1098 (County Surveyor, Registered Land Surveyor, or other duly authorized official)
Office of Register of Deeds, County of, I hereby certify that the within instrument was filed in this office for record on the
(Register of Deeds)