
CERTIFIED	LAND	CORNER	RESTORATION	

		. /		-
Index	No	N.	-	1
IIIuex	INU	I.×.		

History of original corner establishment:

Description of corner evidence found: Found A WELL POINT WITNESS CORNER.

STONE IN ROAD UNDER I.P. WITH X MARK



7	Description of monument and accessories I established to perpetuate the original location of this corner. SET 18" X10" Z.P. A3 THE S Y SEC. COR. SEC. 14, ALSO SET 2" X2" I.P. WITH BRASS CAP A5 WIT. COR. WELL POINT WELL POINT TON RIVE COR. 1978. Signature. Welland F. Lella Title County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of at
	(Register of Deeds)

	~~~~~~	*	
	TJON	RIIE	
1	1	1	
	1	J	
	1	1	
	!		
	1	1	
1	, 1		
1	, I	1	-
1	1	1	
	-+4-		_
1	1 13	l	
1	1	1	
	1	1	
1	1	1	
	1 _	!	-
	ı	1	
	ļ	Į.	
1	1	1	
t.	1	1	
1			
		1	
O = Corner monu	ment resto	ored.	

State of Wisconsin

I YVICLIAM F. KELLY , do hereby certify that on the 14^{Ch} day of SEPTEMBER , 19 78 , I found evidence of the SOUTH - WEST

corner of SECTION 14

Township 30, North, Range ijE , Fourth Principal Meridian,

as described hereon; and that from this evidence

I established a new monument and accessories as described hereon to perpetuate the original

County of LANGLADE

location of this corner.

Resident witnesses:

SS.