LANGLADE COUNTY
U.S. PUBLIC LAND CORNER RESTORATION

The East Quarter corner of Section 25, T. 30 N., R. 11 E., Langlade County, WI.

Corner was: (check all that apply) 4 3011252000

- [ ] Restored through acceptance of an obliterated evidence location.
- [X] Restored through acceptance of a found perpetuated location.
- [ ] Determined to be lost and re-established through proportionate methods.
  Show bearings and distances to PLSS corners used for proportioning, and show original distances).
- [ ] Restored/recovered/re-established in a location that differs from a previously established position.
  (Show difference in plan view below).
- [ ] Check here if addition information is shown on the reverse side of this form.

Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of the corner.

The original corner was established in 1853 by William J. Neeley. Original bearing trees were a birch, 25", S46°E, 19 links and an ironwood, 8" N69°W, 38 links. In 1987, former surveyor Kelly re-established the corner at midpoint between section corners. He "set 1" iron pipe in road below surface" and set an aluminum witness monument to the east and marked three bearing trees. In 1992, Dan Higginbotham found Kellys pipe for the corner and set new 1" iron pipe witness monuments. 07/12/99 D. Tlusty, T. Arnott got magnetic reading in center of road. Dug by hand and found a 10" coil of rusted wire leaning up against the south side of a 10" dia. stone. Stone has "X" chiseled in top. Accepted the stone as found a the best evidence of a previously perpetuated location of the 1/4 corner. Measured ties as shown below.

Physical description of the monument set:

Left existing stone in place.

Describe the accessories used to perpetuate the corner. Include a plan view drawing and accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would aid in future recovery of the corner.



WISCONSIN
DAVID E. TLUSTY
S-1390
Deerbrook
WI
REGISTERED LAND SURVEYOR

10/3/02

I, David E. Tlusty, Registered Land Surveyor, as Langlade County Surveyor, **certify that the corner location on this record was determined by me and that** this U.S. Public Land Survey Monument Record is correct to the best of my **knowledge and belief.**