State of Wisconsin

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. 2 - **35**

History of original corner establishment: Original survey conducted, started November, 1854, finished December, 1854, by James Withrow, deputy Surveyor, found no original evidence as per original government notes.

Description of corner evidence found:

Found old cedar wood post rotted off at ground level with sharpened point. Post located at fence intersection. Presumed post to be old fence post and not the original corner. Set standard Langlade County monument in place of wood post.

11/19/94 D.T. TALKED TO MIKE NORDIN. IN 982, HE FOUND MELINDYS CORNER.

STANDARD LANG CO. 1 1.5' ABOVE GROUND	55	EDWIN R. ABENDROTH S-798 WAUSAU,
(i) 1577'	10.81' SPRUCE	WIS. O.S. SURVERSED BEEFER BEE
Dated at Wausau , Wis., this Signature Elwa Rule Ulus Tritle (County Surveyor, Registered Land Surv	Registered Land Surveyor	Registration No.S=7.98
Office of Register of Deeds, County ofinstrument was filed in this office for record on the at		, I hereby certify that the within
(Register of Deeds)		