(
	4
	J
7	1
	0
420	

CERTIFIED	LAND	CORNER	RESTORATION

History of original corner establishment:

	Index	No. N-15
-	HINESCONS IN	
	WESLEY TRADEWELL S-1342 ANTIGO, WIS.	•
	TRADEWELL SE	,
	S-1342 ANTIGO, WIS.	
	Ed I December H. See	
	Was SUR PROPERTY	

Description of corner evidence found:

Found 6" spike 2" below pavement. Replaced spike with a 3/4"x24" ire rod. Distance to North % corner of Section 15 checks with distance shown on C.T.H. "S" R-O-W plat. Corner checks good with centerline of "S" and Riverside Road.

Description of monument and accessories I	established	to perpetuate	the original l	ocation of t	his corne
P.K. nail in P.P.		Note:	Bearing	s taken	with
D D "3012-15T.	1 (1.4	T) T T)	

P.K. nail in P.P. P.P. #3012-15L	Note: Bearings taken with Recon o - 21/4" O.D. B.I.P. w/Brass O.
T30N PIZE 0 15 17 15 17 165 57	RIVERSIDE ROAD TOURS RIVERSIDE ROAD TOURS TOURS
Dated at Antigo	Wis, this 7th day of August, 19

Signature Medius	A Tredal	Title Rem	istered Land	SurveyorRegistration	No1
(County	y Surveyor, Registered L	and Surveyor, or	other duly authorized	official)	

Office of Register of Deeds, County of	I hereby certify that the with
instrument was filed in this office for record on the	
ato'clock	

(Register of	Deeds)

By......Deputy

State of Wisconsin County of Langlade ss.

I Wesley J. Tradewell, do hereby certify that on the 2nd day of August, 19.79, I found evidence of the South M corner of Section 15.

Township 30, North, Range 12 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original

Resident witnesses:

location of this corner.

	T30N	R12E	
1		1	
			+
1			1
1	,	! !	1
	+	5	<u> </u>
1		1	
		! !	1
		1	1
)	

O = Corner monument restored.