CERTIFIED	LAND	CORNER	RESTORATION
-----------	------	--------	-------------

Index No. R - 25

State of Wisconsin

County of LANGLADE

I WILLIAM F. KELLY do hereby certify that on the 6th day of Nov., 19 81, I found evidence of the $N\epsilon$ corner of Sect. 25 /2 EAST , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:	

	T30N, R/ZE	
	l	
	i	ì
	1	l i
		†
	i	ĺ
	215	
Service Common C	1	1
	1	
	1	1
	i	1
	1	1
	1	

O = Corner monument restored.

History of original corner establishment: ORIGINAL CORNER ESTABLISHED BY WILLIAM J. AERLY IN MAY, 1853

Description of corner evidence found:

A 3" BRASS CAP MONUMENT SET

IN CONCRETE, FOUND IN PLACE.

ESTABLISHED NEW BEARING TREES AND RECOVERED OLD BEARING TREE



Description of monument and accessories I established to perpetuate the original location of this corner.

2	NEW BT'S	B'MAPLE NEW - ST'S A D D D D D D D D D D D D D D D D D D	20"HEMLOCK EXISTING BT SCRIBED	LAND ORRICE THE RISE RISE RISE RISE RISE RISE RISE RIS
NORTH	PK NAIL SET IN GROSS	FIELD 7 3"	BRASS CAP MON., SET IN CONCRETE -	525 530 525 530

Dated at ELCHO	, Wis., this	64	day of	Nov.	, 1981
Signature <i>Mllam & Kill</i> (County Surveyor, Registe	Title Title	COUNTY or, or other duly	SURVEYO	R Registra	tion No. 1098
Office of Register of Deeds, County of instrument was filed in this office for redat	cord on the		day of	, I hereby cert	ify that the within
(Register of Deed	(s)				

.Deputy