County of Langlade...

location of this corner.

I Edwin R. Abendroth do hereby

I established a new monument and accessories

as described hereon to perpetuate the original

		CERTIFIE	LAND	CORNER	RESTORATION
State of Wisconsin	1				

Index	No.	V-	5
HIGGA	140.		

History of original corner establishment:

Original Survey conducted, started, November, 1854, finished, December 1854 by James Withrow, deputy Surveyor, found no original evidence as per original government notes.

Description of corner evidence found:

Intersecting road centerline and fence line.



SUR NOW	190
POWER POLE  \$\tilde{\mathbb{C}} \cdot \begin{array}{cccccccccccccccccccccccccccccccccccc	
Description of monument and accessories I established to perpetuate the original location of this corner.  Standard Lang.  Co. Monument  O.5 Above grd.  VRR Spike  C.T.H."D"	
633/ <sub>17</sub>	19.80
Signature County Surveyor, Registered Land Surveyor Registration No. 3  (County Surveyor, Registered Land Surveyor, or other duly authorized official)	
Office of Register of Deeds, County of, I hereby certify that the instrument was filed in this office for record on the	e withi 19
(Register of Deeds)	

*************				
	T 30	NRI	2 E	
		Ì	1	
		I	1	
	<u> </u>			
	ĺ	i	1	
			I I	
- ;	15	S- -	- + -	
	1	1	1	
		i	į	
		-		
	1	1		
	1	1	I,	
) = Corne	7			