CERTIFIED	LAND	CORNER	RESTORATION	
		COMMEN	RESTORATION	

Index No.	24
-----------	----

State of Wisconsin

County of Langlade ss.

I Raymand J. Halliss, do hereby

certify that on the 324 day of June , 19 78, I found evidence of the £457 //6 corner of Section 1

Township. 31, North, Range

7.5........., Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

731NR9E

O = Corner monument restored.

History of original corner establishment:

ESTABLISHED IN 1937 RESURDEY

Description of corner evidence found:

CORNER DESTROYED By cand clearing operation.

Description of monument and accessories I established to perpetuate the original location of this corner.

Run TRANSIT Line BETween south 14 cor AND SE Section corner of SECTION I-TBIN-RGE AND SEC EAST VIGCOR AT mid Point.

12"X I" GALVANIZED PIPE DROVE IN OID ROAD for TRUE CORNER.

Set 11/2" IRON PIPE WICH BRASS CAP AS W.C., 15 North in old EAST-WEST FANCELINE

TO THE

B.T. 5 TO TRUE CORNER OAK 7" 535"W 50"4" Red Maple 6" 510W 29"9"

4 1 6	- 1	4	The same of the sa
Dated at Antigo	Wis this 3Rd	day of June	10 フタ
	(113., 1113	day or	, 17

Signature Aguera & Mallety Title Registered Land Surveyor, Registration No. 5-685 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

(Register of Deeds)

By......Deput