

CERTIFIED LAND CORNER RESTORATION

Index No. Z-17

State of Wisconsin }  
County of Langlade } ss.

I Anthony B. Kiedrowski, do hereby certify that on the 16<sup>th</sup> day of February, 1978, I found evidence of the SE corner of Section 34 Township 31, North, Range 9, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:

June, 1851, James Marsh set post for the original corner.  
June, 1937, D.A. Hintz set a 3" iron pipe with a brass cap.

Description of corner evidence found:

The search area that was determined after an extensive traverse has been recently bulldozed to provide a snowmobile trail, therefore no evidence was found.

Description of monument and accessories I established to perpetuate the original location of this corner:

This corner was reset by a computed traverse from adjacent found corners, allowing for the curvature of the standard parallel per the BLM Manual of instructions.

SEE REVERSE SIDE.

Set 2"X44" Iron Pipe with Brass Cap.


Dated at Wisc. Rapids, Wis., this 21<sup>st</sup> day of February, 1978.

Signature Anthony B. Kiedrowski Title R.L.S. Registration No. 878  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....  
(Register of Deeds)

By..... Deputy



○ = Corner monument restored.

FORM 985 H. C. MILLER CO., MILWAUKEE

43109340000

43109340000

Ties are to nail and disc driven into tree.



34 CUT OVER AREA 35

