

CERTIFIED LAND CORNER RESTORATION

31-11  
Index No. R-2

State of Wisconsin }  
County of LANGLADE } ss.

I RAYMOND J. HALLISY do hereby  
certify that on the JULY 5 day  
of JULY, 1971, I found  
evidence of the WEST 1/16  
corner of 19 AND 30  
Township 31, North, Range  
11 EAST, Fourth, Principal Meridian,  
as described hereon; and that from this evidence  
I established a new monument and accessories  
as described hereon to perpetuate the original  
location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:

SET BY B.F. DOOR IN SURVEY  
OF CITY OF ANTIGO

Description of corner evidence found:


ROCK IN ROAD 4" X 8" X 24" WITH X ON TOP  
FOUND BY CITY CREW PRIOR TO SEWER INSTALLATION

Description of monument and accessories I established to perpetuate the original location of this corner.

SET (TWO) 2" BRASS CAPS IN CEMENT 53.4 LKS NORTH  
AND 52.6 LKS SOUTH AS WITNESS CORNERS

FORM 985 M. C. MILLER CO., MILWAUKEE

4311190030



○ = Corner monument restored.



Dated at Antigo, Wis., this 5 day of July, 1971

Signature R.J. Hallisy Title REG. LAND SURVEYOR Registration No. 685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within  
instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_  
at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy

