State of Wis							
County of LANGLA	DE ss.						
certify that on the of July evidence of the Secondary of	do hereby 27TH day						
Resident witnesses:							
SEC. 10	SEC.11						
SEC. 15	SEG. 14						

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

31-12

History of original corner establishment:

HIGHWAY CREW FOUND STONE IN CTR. of TOWN RD-STONE HAD X-

Description of corner evidence found:

CREW SET 2-4"X4" CONGRETE MONS EAST OF CORNER 33.0 & .66.0 FT. RESP.

Poss

4RDS.W

Description of monument and accessories \(\pm \) established to perpetuate the original location of this corner.

THERE WAS SET ON THE BRASS PLATE IN THE CONCRETE

REF. NO.1 REF. NO.Z SEC. COR SEL.COR. T3INRIZE 10 111 10/11

15 14 ZRODSW.

Dated at Elcho, Wis., this 28TH day of July 1971 Signature Courty A. Ford Title KEG. LAND SURVEY OR Registration No.S-0001.

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the ______day of ________, 19_______

(Register of Deeds)

ę			
*			