State of Wisconsin

certify that on the 2574

of July , 19 70 , I found evidence of the Northwest //6

corner of Sec. 19

County of LANGLADE

SS.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

SURVEY BY HUTCHINSON IN 1906
NO EXISTING BTS.




31-12

Description of corner evidence found:

FOUND OLD STAKE NEAR ANCIENT FENCE ALSO ROUND STAKE - NO INDICATION IT WAS SQUARED, 1.6 FT. WEST OF FENCE COR.

Description of monument and accessories I established to perpetuate the original location of this corner.



1: Twin MAPLE HD GNB12E 26.5 2= HD. MAPLE 8 NG4W 14.0 3= ELM 18N 712W 24.3

4 = HD. MAPLE 10 516 2W 7.2

ALL TREES BLAZED & SCRIBED NBT

| Dated at ELCHO, | Wis., this | day of | JULY | 10 70 |
|--|---------------|---|---------------------|------------|
| Signature (County Surveyor, Registered | Title KEG. L. | AND SURVEYOR er duly authorized official) | Registration N | Vo. 5-0001 |
| Office of Register of Deeds, County of instrument was filed in this office for recore at | | | I hereby cortife 4h | a |
| | | | | |
| (Register of Deeds) | | | | |
| n . | | | | |