

CERTIFIED LAND CORNER RESTORATION

31-13

Index No. J-11

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

I, Raymond J. Hallisy, do hereby certify that on the 3rd day of July, 1971, I found evidence of the 1/4 corner of Section XXXIX 9 & 16 Township 31, North, Range 13E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found wood stake standing marked 1/4 S 16 9 WCD Location poster on cedar N50E 25' 10"


Resident witnesses:

.....
.....
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap and put stake alongside

BT's to corner
Cedar 10" N50E 25 Feet 10 inches
Spruce 10" N74W 32 Feet
BT's faced at base of tree and scribed BT



FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 3rd day of July, 1971.

Signature R. J. Hallisy Title Reg. Land Surveyor Registration No. 685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

