CERTIFIED LAND CORNER RESTORATION

State of Wisconsin


County of Langlade

I...Raymond J. Hallisy , do hereby certify that on the _____l9th ____day corner of Section 29 Township....., North, Range, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

SS.

Resident witnesses:

Max Johnson



 \bigcirc = Corner monument restored.

History of original corner establishment:

Corner set by M. Hutchinson on October 21, 1909 Square 6" post scribed 1/4
B.T Tamarack 8" N58\frac{1}{4}\text{W} 49\frac{7}{4}\text{lks}

Description of corner evidence found:

Square post as set by Hutchinson. Top in fair shape - Point in excellent shape Also B.T. as described but now about 12" in diameter Faced old B.T. at breast height with

Description of monument and accessories I established to perpetuate the original location of this corner. New corner: 2" iron pipe with brass cap marked $N_4^{\frac{1}{4}}$ Sec 29 T31N R13E

B.T.s / Tamarack 8" S 11° E 16ft. 10in. 2 Tamarack 8" N 58° w 9ft. 8in. 3 Tamarack 7" N 70° E 23ft.

Dated at Annigo) /	Wis., this	21	dav of	April	. 19 69
Signature Ray	und LHally	14 Title	Reg. Land	Surveyor	Reg	ristration No. S-685
(Co	unty Surveyor, Registered	Land Survey	or, or other du	ly authorized off	ficial)	
Office of Register of	Deeds/County of	y			, I hereby	certify that the within
nstrument was filed .to'clock	in this office for reco	rd on the		day of	t	, 19
.t o clock						
	(Register of Deeds)					