Certify that on the 26% do hereby
of MAY , 19 B1 , I found evidence of the West 1/4
corner of Section 19
Township 32 , North, Range 9 East , Fourth Principal Meridian
as described hereon; and that from this evidence I established a new monument and accessories
as described hereon to perpetuate the origina location of this corner.
Resident witnesses:
T32N R9F
T32N, R9E
♦ + 9
O - Corner monument restored

State of Wisconsin

County of LANGLADE

CERTIFIED LAND CORNER RESTORATION

Index No. P-1


History of original corner establishment:

ORIGINAL CORNER ESTABLISED
BY HIRAM C. FELLOWS IN SEPT., 1860.

6"x6" GRANITE MONUMENT SET ON
RESURVEY OF LINCOLN COUNTY IN 1930'S
BY LINCOLN COUNTY HWY. DEPT.

Description of corner evidence found:

REPLACED GRANITE STONE
WITH 2" x 18" IP AND R.R. SPIKE,
SET 2 - 11/2" x 42" BLACK IRON
PIPES WITH BRASS CAP WITNESS
MONUMENTS.



Description of monument and accessories I established to perpetuate the original location of this corner.

NORTH	WIT COR COR 33' (E/W) WEST 1/4 COR SECT + 19 T32N, R9E 5-26-81 WIT. MON. WE K
Dated at ELCHO	, Wis., this 26th day of MAY , 19.81
Signature William S. Kelly	Title COUNTY SURVEYOR Registration No. 1098
Office of Register of Deeds, County of instrument was filed in this office for reconstruction o'clock	, I hereby certify that the within ord on the
(Register of Deeds)	
D	Deputy