O = Corner monument restored.

State of Wisconsin

Index No. C - 19

History of original corner establishment:

CORNER NOT ESTABLISHED DURING ORIGINAL SURVEY.

Description of corner evidence found:

SET A 2" x 42" & ALUMINUM CAP


MONUMENT. MARKED 3 BT'S.

OR SET AT INTERSECTION

OF E-W & N-S 1/4 LINES

FROM O.T. CONTROL SURVEY

(Register of Deeds)



Description of monument and accessories I established to perpetuate the original location of this corner.

1	ALL BT'S NEW		Z" ALUM.	LANGLADE CO.	ENER
NORTH	PK IN "X"	2" ALUM. 52" STONE CAP OC 580°E 20.0.  10" MARLE  6" MAPLE	10"MAPLE	T32N-1  CENT. + S  SECT. =  11-10-8  W F K  SURVEY M	R9E SECT. 2
Date	d at ELCHO	, Wis., this 10 14		OVEMBER	, 19.82
Signature William A. Kelly Title County Surveyor Registration No. 1098  (County Surveyor, Registered Land Surveyor, or other duly authorized official)					
nstrı		for record on the			

...Deputy