O = Corner monument restored.

State of Wisconsin

County of LANGLACE

Range ridian, idence ssories	
riginal	

CERTIFIED LAND CORNER	RESTORATION	SCONS	Index No. 12-17
History of original corner establishmen	it:	WILLIAM F. KELLY	
WEBC4 1903 SET LIGHT 10×16×20 + ON TOP	No.	S1098 ELCHO, WIS.	
Description of corner evidence found: CORNER ESTABLISHED B	W OWENS - ILLINOIS	PROM SURVEY RE	CORDS OF M. HUTCH

N	7"HARD MAPLE SET 2" × 42" BLACK PIPE WITH BRASS CAP MARKED: 15.47. SUPER STATES G"HARD MAPLE G"HARD MAPLE G"HARD MAPLE G"HARD MAPLE G"HARD MAPLE G"HARD MAPLE	?e\ .9E 177
Da	ed at ELCHO, Wis., this GTH day of SEPTEMBER, 1977	
Sig	ature Milliam & Rully Title Re6 is TERED LAND SURVEYOR Registration No. 5 10 98 (County Surveyor, Registered Land Surveyor, or other duly authorized official)	3
ins	e of Register of Deeds, County of	
	(Register of Deeds)	
D.	Deputy	