

CERTIFIED LAND CORNER RESTORATION


32-9 Index No. D-5

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy do hereby certify that on the 15th day of July, 1972, I found evidence of the S 416 corner of S 16 Township 32, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:

Corner Set by Ripco Paper Co.

Description of corner evidence found:

1" pipe with 2" Aluminum Cap

BT's To Witness Corner

6" Ash S 72 E 11.2 FT

8" H. Maple N 45 E 17 FT

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT To Witness Corner

8' Hard Maple N 72 E 32.5 FT

Corner Marked



Dated at Antigo, Wis., this 15th day of July, 1972.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-00685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy